

account possessa accepted session presental presental presental possesse possesse respected basesses



DEVELOPMENT OF A HIGH-TEMPERATURE RESISTANT (700°F), CORROSION-PREVENTIVE ORGANIC COATING

Stephen J. Spadafora

Air Vehicle and Crew Systems Technology Department NAVAL AIR DEVELOPMENT CENTER Warminster, PA 18974-5000

11 JULY 1987

FINAL REPORT Project No. RS34A52 Work Unit ZM540

Approved for Public Release; Distribution unlimited

Prepared for
NAVY EXPLORATORY DEVELOPMENT PROGRAM
AIRBORNE MATERIALS
(NA2A)
NAVAL AIR DEVELOPMENT CENTER
Warminster, PA 18974-5000



NOTICES

REPORT NUMBERING SYSTEM - The numbering of technical project reports issued by the Naval Air Development Center is arranged for specific identification purposes. Each number consists of the Center acronym, the calendar year in which the number was assigned, the sequence number of the report within the specific calendar year, and the official 2-digit correspondence code of the Command Office or the Functional Department responsible for the report. For example: Report No. NADC-86015-70 indicates the fifteenth Center report for the year 1986 and prepared by the Systems and Software Technology Department. The numerical codes are as follows:

CODE	OFFICE OR DEPARTMENT
00	Commander, Naval Air Development Center
01	Technical Director, Naval Air Development Center
02	Comptroller
05	Computer Department
07	Planning Assessment Resources Department
10	Anti-Submarine Warfare Systems Department
20	Tactical Air Systems Department
30	Battle Force Systems Department
40	Communication & Navigation Technology Department
50	Mission Avionics Technology Department
60	Air Vehicle & Crew Systems Technology Department
70	Systems & Software Technology Department
80	Engineering Support Group

PRODUCT ENDORSEMENT - The discussion or instructions concerning commercial products herein do not constitute an endorsement by the Government nor do they convey or imply the license or right to use such products.

APPROVED BY:

W. F. MORONEY

wroney DATE: 5 March SS

CAPT, MSC, U.S. MAVY

SECURITY CLASSIFICATION OF THIS PAGE

NADC 87171-60

N acio			KEPOKI DOCUK	MENTATION F	AGE					
Ta. REPORT SECU	IRITY CLASSIF	ICATION		16 RESTRICTIVE MARKINGS						
	LASSIFIED			N/A						
2a. SECURITY CL	ASSIFICATION	AUTHORITY		3. DISTRIBUTION AVAILABILITY OF REPORT						
The DECLASSIEICA	ATION / DOW	NGRADING SCHEDU	F	1	OR PUBLIC F	•				
ZU. DECLASSIFICA	X110147 00441	יטייים זכוייטיי	••	DISIKIBULI	ON UNLIMITE	עצ				
4. PERFORMING	ORGANIZATK	ON REPORT NUMBE	R(S)	5. MONITORING	ORGANIZATION R	EPORT NUMBE	ER(S)			
NAD(C- 87171-€	50		N/A						
6a. NAME OF PE	REORMING C	RGANIZATION	6b. OFFICE SYMBOL	7a. NAME OF MO	NITORING ORGA	NIZATION				
NAVAL AIR	DEVELOP	ÆNT .	(If applicable)							
	CENTE	ER	6062	N/A			·			
6c. ADDRESS (Cit	ty, State, and	ZIP Code)		76. ADDRESS (Cit	y, State, and ZIP	Code)				
7.14 D.I	MINOMPR	D. 1007/ 500	0	N/A						
WAR	MINSTER,	PA 18974-500	O	N/A						
Ba. NAME OF FU			8b. OFFICE SYMBOL (If applicable)	9. PROCUREMENT	INSTRUMENT ID	ENTIFICATION	NUMBER			
		ALS PROGRAM	,,	N/A						
Bc. ADDRESS (Cit	ry, State, and	ZIP Code)		10. SOURCE OF F	UNDING NUMBER	RS				
NAVAL AIR I	DEVELOPME	ENT CENTER		PROGRAM	PROJECT	TASK	WORK UNIT			
WARMINSTER	, PA 189	74-5000		ELEMENT NO.	NO.	NO.	ACCESSION NO.			
				<u></u>	R534A52	ل	ZM 540			
(U) DEVEL 12. PERSONAL A	LOPMENT (STEPHEN J. S	OVERED	14. DATE OF REPO	RT (Year, Month)		ORGANIC COATI			
(U) DEVEI	LOPMENT (AUTHOR(S) EPORT	OF A HIGH TEM STEPHEN J. S 13b. TIME CO FROMOCT	PADAFORA OVERED	ANT (700°F), 14. DATE OF REPO 1987, July	RT (Year, Month)					
(U) DEVEL 12. PERSONAL A 13a. TYPE OF RE FINAL	LOPMENT (AUTHOR(S) EPORT	STEPHEN J. S 13b. TIME CO FROM OCT	PADAFORA DVERED 84 TO SEP 86	14. DATE OF REPO 1987, July	RT (<i>Year, Month</i> , y 11	, Day) 15. PA	GE COUNT			
(U) DEVEL 12. PERSONAL A 13a. TYPE OF RE FINAL 16. SUPPLEMENT	LOPMENT (AUTHOR(S) EPORT TARY NOTAT	STEPHEN J. S 13b. TIME CO FROM OCT	PADAFORA DVERED 84 TO SEP 86	14. DATE OF REPO 1987, July	RT (Year, Month, y	Day) 15. PA	GE COUNT			
12. PERSONAL A 13a. TYPE OF REFINAL 16. SUPPLEMENT	LOPMENT (AUTHOR(S) EPORT TARY NOTAT	STEPHEN J. S 13b. TIME CO FROM OCT ION	PADAFORA DVERED 84 TO SEP 86 18. SUBJECT TERMS (HIGH TEMPERA	14. DATE OF REPO 1987, July Continue on revers	RT (Year, Month, y	Day) 15. PA	GE COUNT			
13a. TYPE OF REFINAL 16. SUPPLEMENT	LOPMENT (AUTHOR(S) EPORT TARY NOTAT COSATI (GROUP J3	STEPHEN J. S 13b. TIME COFROMOCT ION CODES SUB-GROUP	PADAFORA DVERED 84 TO SEP 86 18. SUBJECT TERMS (HIGH TEMPERA CORROSION PR	14. DATE OF REPO 1987, July Continue on revers TURE RESISTAL	RT (Year, Month, y	Day) 15. PA	GE COUNT			
13a. TYPE OF REFINAL 16. SUPPLEMENT	LOPMENT (AUTHOR(S) EPORT TARY NOTAT COSATI (GROUP J 3 Continue on	STEPHEN J. S 13b. TIME COFROMOCT ION CODES SUB-GROUP	PADAFORA DVERED 84 TO SEP 86 18. SUBJECT TERMS HIGH TEMPERA CORROSION PR and identify by block	14. DATE OF REPO 1987, July Continue on revers TURE RESISTAL OTECTION	RT (Year, Month, y 1) e if necessary an	Day) 15. PA	block number) IC COATING			
12. PERSONAL A 13a. TYPE OF REFINAL 16. SUPPLEMENT 17 FIELD 19 ABSTRACT (Grain the tem pro The	COSATION COS	STEPHEN J. S 13b. TIME COFROMOCT ION CODES SUB-GROUP reverse if recessary t materials utings provide erature cure. e poor protect cure and specthey are not for these app	PADAFORA DVERED 84 TO SEP 86 18. SUBJECT TERMS (HIGH TEMPERA CORROSION PR	Continue on reverse TURE RESISTAL OTECTION number) perature range, but are descan be earrosion. When equipment ost aircraft air-dry systems	ref (Year, Month, y	organian dapply and and air- in manufatouchup	block number) IC COATING deficiencies. I require -dry, but ing high- acturing applications.			
12. PERSONAL A 13a. TYPE OF REFINAL 16. SUPPLEMENT 17 FIELD 19 ABSTRACT (Cer. a h the tem pro The sys	COSATION GROUP Continue on Curren amic coal igh-tempy provide perature cesses, refore, tems provided to the coal igh of the cesses of the ce	STEPHEN J. S 13b. TIME COFROMOCT ION COOES SUB-GROUP reverse if recessary t materials utings provide erature cure. e poor protect cure and specthey are not for these approvide barrier	PADAFORA OVERED 84 TO SEP 86 18. SUBJECT TERMS (HIGH TEMPERA CORROSION PR and identify by block (sed in this tem good protectio Standard pain tion against co cial applicatio practical for molications, the protection again	Continue on reversions. Continue on reversions TURE RESISTAL OTECTION number) perature range n, but are d ts can be ear rrosion. When equipment ost aircraft air-dry systemst the envi	e if necessary and of necessary and necessary	organian dentify by ORGANIanificant deply and airlist requiring anufactouchup amarily use	block number) C COATING deficiencies. I require dry, but ing high- acturing applications. ed. These			
12. PERSONAL A 13a. TYPE OF REFINAL 16. SUPPLEMENT 17 FIELD 19 ABSTRACT (Cer. a in the tem pro The sys	COSATION GROUP On Curren amic coa igh-temp y provide perature cesses, refore, tems pro	STEPHEN J. S 13b. TIME COFROMOCT ION COOES SUB-GROUP reverse if recessary t materials utings provide erature cure. e poor protect cure and specthey are not for these approvide barrier	PADAFORA OVERED 84 TO SEP 86 18. SUBJECT TERMS (HIGH TEMPERA CORROSION PR and identify by block (sed in this tem good protectio Standard pain tion against co cial applicatio practical for m protections, the protection again	Continue on reversions. Continue on reversions. TURE RESISTAL OTECTION number) perature range, but are did to can be earrosion. When equipment ost aircraft air-dry systemst the environst the envi	RT (Year, Month, y !!) If if necessary and y is in the significult to sily applied in the sily applied i	organian dentify by ORGANIanificant deply and airlist requiring anufactouchup amarily use	dock number) C COATING deficiencies. deficie			
134. TYPE OF REFINAL 16. SUPPLEMENT 17 FIELD 19 ABSTRACT (Cerain the tempro The sys 20 DISTRIBUTION 20 UNCLASSI 22a. NAME OF	COSATION GROUP COSATION GROUP Continue on Current amic coal igh-tempy provide perature desses, refore, tems pro Convavallabilities provided the perature desses and the perature desses are fore, tems provided the perature desses are fore.	STEPHEN J. S 13b. TIME COFROMOCT ION COOES SUB-GROUP reverse if recessary t materials utings provide erature cure. e poor protect cure and specthey are not for these approvide barrier ILLITY OF ABSTRACT IED SAME AS	PADAFORA OVERED 84 TO SEP 86 18. SUBJECT TERMS (HIGH TEMPERA CORROSION PR and identify by block (sed in this tem good protectio Standard pain tion against co cial applicatio practical for m protections, the protection again	Continue on reversions. Continue on reversions. TURE RESISTATOTECTION number) perature range, but are done to can be earrosion. When the equipment of aircraft air-dry systemst the environment.	RT (Year, Month, y	organia dentify by ORGANIa nificant deply and airls required in manufactouchup marily use continued CATION	dock number) IC COATING deficiencies. I require -dry, but ing high- acturing applications. ed. These			

All other editions are obsolete

ABSTRACT (Cont.)

CONTRACTOR OF THE PROPERTY OF

An organic coating has been developed that air dries at room temperature, is thermally stable up to 700°F and provides corrosion protection far superior to similar materials used for this type of application. The developed coating is based on a unique resin blend which can withstand exposure to 700°F. The blend of pigments used in this coating provides corrosion protection by both barrier and chemical means. This coating was initially designed to be used on steel aircraft engine components that are periodically subjected to temperatures in the 500°F to 700°F range. Additional testing, however, has shown that this coating can also be used on aluminum substrates.

TABLE OF CONTENTS

	Page	
LIST OF TABLES	i	
LIST OF FIGURES	ii	
INTRODUCTION	1	
TEST METHODS	1	
THERMAL CYCLING TEST	1	
DRYING TIME	2	
ADHESION	2	
CHEMICAL RESISTANCE	2	
IMPACT FLEXIBILITY	2	
CORROSION RESISTANCE	3	
PENCIL HARDNESS TEST	3	
DISCUSSION OF COATING DEVELOPMENT	3	
RESIN SYSTEM DEVELOPMENT	3	
PIGMENT SYSTEM DEVELOPMENT	4	
FINAL COATING DEVELOPMENT	10	
DISCUSSION OF COMPARISON OF HTC'S PERFORMANCE	21	
CONCLUSIONS	27	
FUTURE EFFORTS	27	TE TE
REFERENCES	32	~ E
ACKNOWLEDGEMENT	32	lon For
•	·	

*Ortginel restains color place of All Elisar product from Fill by in Samek and

int stone

A state of the Constant of the Cons

LIST OF TABLES

		ra	age
TABLE	I	Candidate Resin Properties	5
TABLE	II	First Resin Blend Series	7
TABLE	III	Second Resin Blend Series	7
TABLE	IV	Third Resin Blend Series	7
TABLE	V	Thermally Stable Pigments	11
TABLE	VI	Statistical Design For Optimum PVC Determination	11
TABLE	VII	PVC Coating Series Formulations	12
TABLE	VIII	PVC Coating Series Properties	13
TABLE	IX	PVC Coating Series Corrosion Resistance Properties	14
TABLE	X	Comparison of Single Pigment Coating Properties	16
TABLE	ХI	Single Pigment Coating Corrosion Resistance Properties	17
TABLE	XII	Zinc-Dust/Aluminum Coating Series Formulations	18
TABLE	XIII	Zinc-Dust/Aluminum Coating Series Properties	19
TABLE	XIV	Zinc-Dust/Aluminum Coating Series Corrosion Resistance Properties	20
TABLE	XV	Comparison of High Temperature Coatings (5 Day - 700 F Cycle)	22
TABLE	IVX	Corrosion Resistance Test Results (5 Day - 700 F Cycle)	23
TABLE	XVII	Comparison of High Temperature Coatings (1 Hour $@ 700 \ \text{F}$).	25
TABLE	XVIII	Corrosion Resistance Test Results (1 Hour @ 700 F)	26
TABLE	XIX	Comparison of High Temperature Coatings (5 Day - 400/500F Cycle)	28
TABLE	XX	Corrosion Resistance Test Results (5 Day - 400/500 F Cycle)	29
TABLE	XXI	Comparison of High Temperature Coatings (7 Days @ 70 F)	30
TABLE	XXII	Corrosion Resistance Test Results (7 Days @ 70 F)	31

LIST OF FIGURES

			Page
Figure	1.	Tricoordinate Graph With First Resin Blend Series	. 6
Figure	2.	Graph Showing Region of Thermal Stability	. 8
Figure	3.	Specific Area of Thermal Stability	. 9
Figure	4.	Test Panels For Corrosion Resistance Test	. 24

INTRODUCTION

Various areas of naval aircraft are routinely subjected to high temperatures. The epoxy primer (MIL-P-23377) and polyurethane topcoat (MIL-C-83286) paint system currently applied to Navy aircraft was Jesigned to withstand exposures to temperatures up to 250°F for long durations (10 to 20 hours) and 350°F for short durations (1 to 2 hours). However, a survey of Naval Aviation Depots and airframe manufacturers indicated a need for a coating that would resist temperatures of 500 to 700°F and also protect the underlying metallic substrate from corrosion. One specific use for this material is on low carbon alloy steel heat shields around aircraft turbine Currently, two materials are being used for this application: a silicone based aluminum paint covered under Federal specification TT-P-28, and Sermatel W, ceramic based material. Both of these materials have costly deficiencies. TT-P-28 can be spray applied, air-dries, and is thermally resistant. However, it provides poor corrosion protection and marginal film properties, therefore requiring frequent repair. Sermatel W is thermally resistant and provides good corrosion protection; but it requires a hightemperature cure and is very costly and difficult to apply. In addition, Sermatel W is extremely difficult to repair. Therefore, there is a need to find or develop a material for these types of application.

SASSION ACCORD VIRIARA VILLALA SESSESSE PITTAL

The coatings industry was surveyed for existing coatings that would provide the necessary temperature and performance requirements for this type of coating. Candidate materials were obtained from paint suppliers and evaluated. These materials proved to be inadequate for this application. Therefore, a new material had to be develop. To accomplish this task, samples of resin systems exhibiting good thermal properties were obtained. These materials were identified during the industry survey and consisted of silicones, silicone-copolymers, and polyimide resins. Along with these resins, thermally-stable pigments were also obtained. These materials were then used to formulate a coating with the desired properties. This report first describes the in-house development of this coating and then compares its performance with the current materials.

TEST METHODS

ではないと、これのないとは、一般な人人人人人人とはなかなからない。 | 1997年には、

The substrates used to evaluate the properties of these coatings were: bare 1020 carbon steel (unpretreated), bare 2024-T3 aluminum alloy, and 2024-T0 aluminum alloy. The 2024-T3 aluminum panels were pretreated with a chromate conversion coating in accordance with specification MIL-C-5541 using materials conforming to specification MIL-C-81706. The 2024-T0 aluminum panels were anodized in accordance with specification MIL-A-8625, Type II. The coatings were applied by conventional air-spray to a dry-film thickness of 1.4 \pm 0.4 mils. With the exception of the thermal cycling test, the physical properties of each coating were determined in accordance with test methods from the American Society for Testing and Materials (ASTM) and Federal Test Method Standard (FTMS) No. 141B.

Thermal Cycling Test

Since this type of coating would have to withstand repeated cyclic exposures to 700°F in service, a laboratory test method was developed that

simulated service conditions. Coated test panels were cyclically exposed for 8 hours at $700^\circ F$ and then 16 hours at room temperature $(70^\circ F)$. This cycle was repeated five times for a total test time of 120 hours (40 hours at $700^\circ F$ total). The test panels were evaluated at the end of each test cycle for blistering, uplifting, or other forms of coating failure. The coatings were rated using a system that correlated to the length of time before failure in the thermal stability test. The rating scale ranged from 1 to 10; where 1 corresponded to failure during the first cycle (<1 day), 2 failed between the first and second cycles, and so on up to 10 which passed all 5 days of exposure. Another less severe, thermal cycling test was developed for comparison of the final coating properties with those of the current materials. The cycle in this test consisted of 5 hours at $400^\circ F$, 3 hours at $500^\circ F$, and 16 hours at room temperature and was also repeated five times.

2) Drying Time (ASTM D 1640)

Dry-hard time of the coating was measured and is defined as the period of time from application until the film cannot be permanently marred using firm thumb pressure. At this point, a painted component can be handled without causing permanent damage to the coating.

3) Adhesion (FTMS 6301, ASTM D 2197A)

Adhesion to steel and aluminum substrates was measured by the tape test and the scrape-adhesion test. For the tape test, an "X" was scratched between two parallel, scribed lines approximately one-inch apart on the test panel. Then, a strip of 3M-250 masking tape was applied over the scribe marks with firm thumb pressure and removed with one quick motion. Removal of the coating from the substrate is grounds for failure. This test was performed on both dry specimens and on specimens that were immersed in water at 70°F for 24 hours. For the scrape-adhesion test, a weighted stylus was scraped across the test panel from bare substrate onto a coated section. The minimum weight to cut through the coating to the substrate is the scrape-adhesion value.

4) Chemical Resistance

Chemical resistance was evaluated by exposing coated panels to various fluids for a period of one day. Resistance to hydraulic fluids and lubricating oils was determined by immersing coated panels in MIL-H-83282 hydraulic fluid at 150°F and MIL-L-23699 lubricating oil at 250°F. The coatings were then observed for softening or other signs of film degradation. Resistance to hydrocarbons was ascertained by rubbing cloth rags soaked in methyl ethyl ketone (MEK) and MIL-T-5624, Grade JP-4 aviation fuel back and forth across the surface of the panel ten times. Complete removal of the coating from the panel represented failure in these tests. Water resistance of the coatings was determined by immersing coated test specimens in distilled water at room temperature for 24 hours. The panels were removed and immediately examined for signs of blistering or softening of the coating.

5) Impact Flexibility (FTMS 6226)

Impact resistance of the coatings was measured by means of a GE impact tester. This test was performed on the anodized, 2024-TO aluminum alloy

panels. The results are given as the maximum percentage elongation that the coating can withstand without cracking.

6) Corrosion Resistance (ASTM B 117)

Coated panels were thermally aged, scribed with an "X" down to bare substrate on the bottom one-third of the panel and mounted in a 15 degree rack. These panels were then exposed to a 5% NaCl salt spray environment. Periodically these panels were removed, and the surfaces were evaluated for evidence of corrosion products to determine the corrosion resistance of the coating.

7) Pencil-Hardness Test (ASTM D 3363)

The pencil-hardness of a coating gives an indication of the film's integrity. The hardness value is obtained by firmly holding the pencil against the surface at a 45-degree angle and pushing across the surface in an even stroke. The hardness rating of the pencil that does not permanently scratch the surface is the pencil-hardness of the coating.

DISCUSSION OF COATING DEVELOPMENT

Development of the final coating was performed in three stages: resin system development, pigment selection and final coating development.

Resin System Development

The first stage in this process was the development of a thermallystable resin system with the appropriate binder properties (i.e. adhesion, drying characteristics, film integrity, etc.). The requirements for this binder system were: 1) The coating must dry tack-free at room temperature (70°F) in less than eight hours with sufficient integrity to be handled without inflicting permanent damage; 2) The coating must be adherent to both steel and aluminum substrates; and 3) The coating must maintain its integrity up to 700°F for prolonged periods (eight hours) and multiple thermal cycles. Candidate resins investigated for this coating consisted of polysiloxanes, silicone copolymers, and polyimides. To screen these materials, the resins were applied to several steel panels as clear coatings and allowed to air-dry for a minimum of 48 hours. Then, these panels were subjected to the 70 to 700°F thermal cycling test which provided information on how well the unpigmented material performed when subjected to high temperatures and thermal fatigue. In addition, the film properties (i.e. adhesion, drying time, and pencil hardness) of the candidate binders were analyzed both before and after thermal cycling.

After initial screening, the polyimide resins were deleted from further investigation for several reasons. First, they would not form clear homogeneous films when applied to the steel test panels. Even the addition of surface active agents did not solve this non-uniformity problem. Second, the resultant films would not dry-hard. After several days, they still remained tacky. Finally, after exposure to thermal cycling, the coatings were brittle and filled with air-voids.

All of the silicone and silicone copolymer resins formed clear homogeneous coatings when spray applied to the test panels. However, they all lacked at least one or more of the required binder properties. Table I shows the specific properties of the materials tested. The silicone copolymers had good room-temperature coatings properties. However, they lacked thermal stability. The silicones could be grouped into two categories. Although some resins were thermally stable, they remained tacky at room temperature with no film integrity and had only marginal film properties after thermal cycling. The rest of the resins had good thermal stability and were dry-hard at room temperature, but had poor coatings properties both before and after thermal cycling. Since no individual resin could provide the required binder properties, polymer-blend technology was incorporated to provide an appropriate binder system. The initial test results, along with information provided in the product literature, were used to choose the optimum materials for the polymer-blend formulations. Three resins were chosen for further binder development. The McCloskey 385-50E silicone-alkyd resin was selected because it had the best room-temperature film properties; although it lacked thermal stability. The G.E. SR 125 silicone resin was chosen because it performed the best in the thermal cycling test. Even though it remained tacky at room temperature, the SR 125 resin cured to a flexible film during thermal cycling. The G.E. SR 141 silicone dried at room temperature, forming a very brittle film. This material had good thermal resistance, but only survived one day of thermal cycling. This failure was attributed to the brittle nature of the coating. Combining this resin with the SR 125 and the 385-50E resins would enhance both the high-temperature resistant and the as-applied properties of the coating.

A simplex-design statistical screening method was used to obtain the polymer-blend formulations (reference (1)). Figure 1 is a tri-coordinate graph showing the first series of resin blends. Once prepared, these resin combinations were thinned to spray viscosity with toluene and applied to steel panels as clear coatings to a dry-film thickness of 1.0 to 1.5 mils. After 48 hours at room temperature, the coated panels were subjected to the 70 to 700 F thermal cycling test. The coatings were rated using a scale from ! (worst) to 10 (best). This rating system correlated to the length of time before failure in the thermal stability test. Table II contains the first series of resin blend formulations and their thermal cycling ratings. From these results, a composition region of thermal stability was identified. This region is shown in Figure 2. The next series of formulations were prepared from this region and tested to determine their thermal stability (see Table III). The results from the second series of formulations narrowed down the region of thermal stability to a specific area. The last series of resin formulations was taken from this area. This information appears in Table IV and Figure 3. All of the resin systems tested in this area passed five days in thermal cycling. The drying characteristics and film integrity of all the resin blends that rated a ten in the thermal cycling test were then evaluated; and five potential systems were identified. They were formulations R-08, R-15, R-22, R-24, and R-25. These systems and were used in the final coating development.

Pigment Selection

Pigment selection consisted of first determining a pigment system that was thermally stable up to 700° F, in addition to providing the required corrosion protection. The initial screening of candidate pigments was

TABLE I CANDIDATE RESIN PROPERTIES

ADHESION DRY TAPE (>1WEEK)		PASS	PASS	PASS			PASS	PASS	
PENCIL HARDNESS (4BB,H4H) (1DAY) (1WEEK)	1	<4B	38	<4B	1	1	28	82	
PENCIL (4B) (1DAY)		<4B	38	48	1	1	<4B	<4B	
THERMAL STABILITY AY-70 TO 700 F CYCLE) ANEL #1 PANEL #2	3 DAYS	5 DAYS	1-2 DAYS	<1 DAY	<1 DAY	<1 DAY	<1 DAY	<1 DAY	
THERMAL STABILITY (5 DAY-70 TO 700 F CYCLE) PANEL #1 PANEL #2	4 DAYS	4-5 DAYS	1-2 DAYS	<1 DAY	<1 DAY	<1 DAY	<1 DAY	<1 DAY	
TIME DRY-HARD (HOURS)		>168 HRS	2.0 HRS	4.0 HRS	1		1.0 HRS	1.5 HRS	
DRYING TACK-FREE (HOURS)	>168 HRS	8.0 HRS	1.0 HRS	2.0 HRS	>168 HRS	>168 HRS	0.5 HRS	0.5 HRS	
RESIN TYPE	PUKE SILICONE	PURE SILICONE	SILEPOXY	SILALKYD					
RESIN ID	GEN. ELEC. 112	GEN. ELEC. 125	GEN. ELEC. 141	GEN. ELEC. 240	GEN. ELEC. 882	CARGILL 6260	CARGILL 6247	MCCLOSKEY 385-50E	




FIGURE 1. TRICOORDINATE GRAPH WITH FIRST RESIN BLEND SERIES.

TABLE II FIRST RESIN BLEND SERIES

RESIN FORMULATION NO.	SR 141 RES IN PARTS	SR 125 RES IN PARTS	385-50E RESIN PARTS	THERMAL STAR 5 DAY-70 TO PANEL#1	
R - 01		100.0		8	10
R - 02	100.0			2	2
R - 03	50.0	50.0		2	4
R - 04		50.0	50.0	10	10
R - 05	50.0		50.0	1	1
R - 06	33.3	33.3	33.3	2	3
R - 07	66.7	16.6	16.6	6	i 4
R - 08	16.6	66.7	16.6	10	10
R - 09	16.6	16.6	66.7	1	1
R - 10			100.0	1	1

THERMAL STABILITY RATING SYSTEM: 1=<1 DAY, 2=1-2 DAYS...10=>5 DAYS

TABLE III SECOND RESIN BLEND SERIES

RESIN FORMULATION NO.	SR141 RESIN PARTS	SR 125 RES IN PARTS	385-50E RESIN PARTS	THERMAL STAI 5 DAY-70 TO PANEL#1	
R - 11	40.0	40.0	20.0	5	2
R - 12	10.0	35.0	55.0	1	1
R - 13		75.0	25.0	10	10
R - 14	25.0	75.0		! 2	2
R - 15	10.0	80.0	10.0	10	10
R - 16	22.5	55.0	22.5	, 9	10
R - 17	5.0	60.0	35.0	10	10
R - 18	15.0	45.0	40.0	3*	10
. !			1	1	

THERMAL STABILITY RATING SYSTEM: 1=<1 DAY, 2=1-2 DAYS...10=>5 DAYS * 5-10% FAILURE AT PREEXISTING FLAW

TABLE IV THIRD RESIN BLEND SERIES

RESIN	SR 141	SR 125	385-50E	THERMAL STAR	
FORMULATION	RES IN	RES IN	RESIN	5 DAY-70 TO	
NO.	PARTS	PARTS	PARTS	PANEL#1	
R - 21 R - 22 R - 23 R - 24 R - 25	20.0 10.0 10.0 10.0	70.0 70.0 65.0 85.0 75.0	10.0 20.0 25.0 15.0	10 10 10 10 10	10 10 10 10 10

THERMAL STABILITY RATING SYSTEM:

1 = < 1 DAY, 2 = 1 - 2 DAYS...10 = > 5 DAYS





FIGURE 2. GRAPH SHOWING REGION OF THERMAL STABILITY.



reconstant and self received absolute by course present to

Section 1

accomplished solely by thermal analysis. Both Differential Scanning Calorimetry (DSC) and Thermogravimetric Analysis (TGA) were performed on the potential materials to determine their thermal stability. Table V lists the thermally stable pigments identified from this testing. These pigments were incorporated into coating formulations obtained from a computer program that calculates theoretical optimum coating formulations based on oil absorptions and pigment packing factors. This formulating procedure is described in detail in reference (2). Using these formulations, the coatings were prepared with the resin systems developed above. The pigments were milled into the resin systems using ball/shot milling techniques, with the exception of the leafing aluminum pigment. This material attains the leafing action by its platelet shape which would be destroyed by ball milling. Therefore mechanical stirring was used to disperse this pigment. Once prepared, all of these coatings were applied to steel panels and analyzed for thermal, mechanical, chemical and corrosion inhibiting properties.

Three pigments were eliminated at this point. Titanium dioxide coatings provided only minimal protection against the corrosion process as a barrier coating; and therefore, were dropped from further consideration in this study. Red iron oxide coatings tended to crack and uplift some time after the completion of the thermal cycling test, which resulted in poor performance in the corrosion resistance tests. Further experimentation with red iron oxide coatings with lower pigment volume concentrations still resulted in poor performance in these tests. Consequently, this pigment was also dropped from the investigation. Finally, the leafing aluminum pigment performed far better than the particulate aluminum pigment in these initial coatings. Therefore, the aluminum powder was disregarded in favor of the leafing pigment.

KINGGON DODDZICH BRIDINIA IDZOZIET KINSSSKI BOSODON DIZINALE PRINCO

Finally, the two zinc-dust pigments were analyzed and compared in all five resin systems. In most of these tests, there was little difference between the two materials. However, the Zn101 performed better than the Zn303 in the corrosion resistance tests and therefore, was used for the final coating development.

Final Coating Development

という アンドングラン・アンプログログ・アングラン・アングラン・アングラン・アングラン・アングラン・アンプログラン・アング

To facilitate in the development of the final coating system only the #25 resin system was used with the two pigment types (zinc dust and leafing aluminum). This resin blend was selected because it was centrally located in the area outlined by the five approved resin systems.

The optimum pigment volume concentrations (PVC's) for the zinc-dust and the leafing aluminum pigments had to be determined. Formulations using the theoretical prediction program stated earlier were used as upper boundary limits for a multi-level factorial design using pigment type and solvent type versus PVC. Table VI shows this factorial design. The formulations for these coatings are listed in Table VII and the test results of these materials appear in Tables VIII & IX.

Analysis of the data in Tables VIII and IX for the zinc-dust coatings showed that the optimum properties for this pigment were obtained using a PVC of 40%. Above this PVC, the physical properties began to deteriorate; and, below this PVC the corrosion resistance properties were significantly decreased. Also, these test results indicated that there was vertually no

TABLE V THERMALLY STABLE PIGMENTS

PIGMENT TYPE	PIGMENT MANUFACTURER	PIGMENT IDENTIFICATION
RED IRON OXIDE	PFIZER CO.	#R-2199
ALUMINUM POWDER	ALCAN POWDERS AND CHEMICALS	AL. POWDER #9900
LEAFING ALUMINUM	ALCAN POWDERS AND CHEMICALS	AL. FLAKE #515
TITANIUM DIOXIDE	E. I. DUPONT INC.	#R-960
ZINC DUST	LDL TECHNOLOGY INC.	ZN-101 AND ZN-303

TABLE VI STATISTICAL DESIGN FOR OPTIMUM PVC DETERMINATION

PIGMENT VOLUME CONCENTRATION	PIC	SOLVENTS GMENTS ALCAN #515	I .	AR SOLVENTS GMENTS ALCAN #515
60	x	x	x	X
50	X	Х	X	у
40	Х	X	х	X
30	Х	Х	X	X
20	X	X	X	X
10	x	X	X	x

TABLE VII PVC COATING SERIES FORMULATIONS

PIGMENT VOLUME CONC.	09	50	40	30	20	10	50	40	30	09	50	40	30	20	10	50	40	30
GHT CELLOSOLVE ACETATE	30	30	30	10	10	10	30	30	10	30	30	30	10	10	10	30	30	10
SOLVENTS PARTS BY WEIGHT E MEK CEL	25	20	20	5	5	5	25	20	5	1	-	-			1	-		
PAI TOLUENE	25	30	30	15	15	15	25	30	51	05	95	90	20	20	20	95	05	20
VTS WEIGHT ALCAN 515					-		63.6	53.8	28.1		-			1		63.6	53.8	28.1
PIGMENTS PARTS BY WEIGHT ALCAN ZN101 515	81.3	5.4 7	0.99	5.55	42.3	24.5				81.3	74.4	0.99	55.5	42.3	24.5		-	-
16HT 385- 50E	2.8	3.8	5.1	6.7	8.7	11.3	5.5	6.9	10.8	2.8	3.8	5.1	6.7	8.7	11.3	5.5	6.9	10.8
RESINS TS BY WELGHT GE 385 SR125 50	14.0	19.2	25.5	33.3	43.2	56.6	27.3	34.7	53.9	14.0	19.2	25.5	33.3	43.2	56.6	27.3	34.7	53.9
PART GE SR 141	1.9	2.6	3.4	4.5	5.8	7.6	3.6	9.4	7.2	1.9	2.6	3.4	4.5	5.8	7.6	3.6	4.6	7.2
SOLVENT	POLAR	POLAR	POLAR	POLAR	POLAR	POLAR	POLAR	POLAR	POLAR	NON-POLAR	NUN-POLAR	NUM-POLAR	NON-POLAR	NON-POLAR	NON-POLAR	NON-POLAR	NON-POLAR	NON-POLAR
NADC FORMULATION NO. 8372-	46-Z1-25-A6	50-21-25-A5	50-21-55-A4	57-21-25-A3	61-21-25-A2	61-21-25-A1	46-A5-25-A5	50-A5-25-A4	71-A5-25-A3	46-Z1-25-A6	50-21-25-A5	50-21-25-A4	57-21-25-A3	61-21-25-A2	61-21-25-A1	46-A5-25-A5	50-A5-25-A4	71-A5-25-A3

ú
C
2
:
E
U
۰
U
ŭ
۵
4
-
Ξ
٠
Ĺ

TABLE VIII PVC COATING SERIES PROPERTIES

				· · · · ·				NAD	C 87	171-	60								
	DI-WATER (77 F)	Ъ	P	P	Ы	Ь	d	Ы	ď	ď	P	ď	Ь	ď	d	d	Ь	d	Ь
RESISTANCE	MIL-L-23699 (250 F)	Ь	ď	Ь	d	Ь	P	ď	Ь	Ь	d	d	d	Ь	d	d	d	d	d
FLUID RESIS	MIL-H-83282 (150 F)	ď	d	ď	Ь	Q.	a.	ď	Ь	Ь	d	ď	d	d	d	d	Q.	Ь	Ь
	JP-5 FUEL (77 F)	ď	Ь	ď	Ь	Ь	Б	Б	Ь	ď	ď	Р	Р	Ь	Ь	Ь	ď	d	Ь
FLEXIBILITY	GE IMPACT %elongation	5	10	40	09	09	09	10	20	20	5	10	07	09	09	09	10	20	40
THERMAL	(5 Days @ 700F)	പ	ď	Ь	Ы	ď	ď	Δ.	ď	Ы	ď	d	d	a.	ď	d	ď	Ь	ď
TESTS	SCRAPE (Kgms)	<.5	0.5	1.0	1.0	1.0	1.0	<.5	1.0	1.0	<.5	0.5	1.0	0.1	1.0	1.0	<.5	0.5	1.0
ADHESION	WET TAPE	Ь	ď	Ь	a	പ	a.	Ь	Ь	Ь	d	Ъ	a.	а	Ы	Ъ	d	Ы	a.
ADH	DRY TAPE	d	Ь	Ь	Ь	ď	Ь	Ь	ď	Ы	Ь	ď	Ь	Ь	Ь	Ь	a.	a	a
DRYING TIME	DRY-HARD (Hrs)	P - 1.0	NP - 2.0	NP - 2.0	NP - 2.0	NP = 2.0	NP - 2.0	NP - 2.0	NP = 2.0	NP - 2.0	NP - 2.0								
NADC	FORMULATION NO. 8372-	46-21-25-A6	50-Z1-25-A5	50-Z1-25-A4	57-Z1-25-A3	61-21-25-A2	61-21-25-A1	46-A5-25-A5	50-A5-25-A4	71-A5-25-A3	46-21-25-A6	50-21-25-A5	50-21-25-A4	57-21-25-A3	61-21-25-A2	51-21-25-A1	46-A5-25-A5	50-A5-25-A4	71-A5-25-A3

TABLE IX PVC COATING SERIES CORROSION RESISTANCE PROPERTIES ASTM #B 117 (5% NaCl SALT SPRAY TEST)

FORMULATION NO. 8372-	STEEL (500 HOURS) SCRIBE AREA	STEEL (500 HOURS) GENERAL COATING SURFACE
46-Z1-25-A6 (P) (Polar solv.)	1 , 2	White residue over panel with a few spots of corrosion on panel
50-Z1-25-A5 (P) (Polar solv.)	1 , 2	White residue over panel with about 5 spots of corrosion on panel
50-21-25-A4 (P) (Polar solv.)	2,3	White residue over panel with about 20 small spots of corrosion on panel
57-Z1-25-A3 (P) (Polar solv.)	4 – WR	Approximately 50 spots of corrosion with rundown over 75% of panel
61-Z1-25-A2 (P) (Polar solv.)	5 – WHR	Many spots of corrosion on surface with heavy rundown over most of panel
61-Z1-25-A1 (P) (Polar solv.)	5 - WHR	Many spots of corrosion on surface with heavy rundown over most of panel
46-A5-25-A5 (P) (Polar solv.)	4 – WR	Approx. 50 small spots of corrosion over panel surface with rundown
50-A5-25-A4 (P) (Polar solv.)	5 – WR	Approx. 100 small spots of corrosion over panel surface with rundown
71-A5-25-A3 (P) (Polar solv.)	5 - WHR	Many spots of corrosion on surface with heavy rundown over most of panel
46-Z1-25-A6(NP)	l , 2	Same as polar solvent results above
50-Z1-25-A5(NP)	1 , 2	Same as polar solvent results above
50-Z1-25-A4(NP)	2,3	Same as polar solvent results above
57-Z1-25-A3(NP)	4 – WR	Same as polar solvent results above
61-Z1-25-A2(NP)	5 - WHR	Same as polar solvent results above
61-Z1-25-A1(NP)	5 - 7HR	Same as polar solvent results above
46-A5-25-A5(NP)	4 - WR	Approx. 100 spots of corr. w/ rundown
50-A5-25-A4(NP)	5 - WHR	Approx. 200 spots of corr. w/ rundown
71-A5-25-A3(NP)	5 - WHR	Same as polar solvent results above

SCRIBE RATINGS:

- 1 No corrosion in scribe
 2 Slight corrosion in scribe
 3 Some corrosion in scribe
 4 Moderate corrosion in scribe

5 - Heavy corrosion in scribe

- WR With rundown from scribe
- WHR With heavy rundown from scribe

difference between the zinc-dust coatings with the polar solvents and the non-polar system.

Determination of the optimum PVC for the leafing aluminum pigment involved experimentation with the solvent system as well as the PVC. The leafing efficiency of the pigment is a function of the wettability of the pigment by the resin in addition to the type and amount of solvent. The leafing nature of the material occurs by the alignment of the pigment in the resin to form a pseudolayer of aluminum (reference (3)). The alignment of the aluminum platelets is enhanced by the incompatability of the resin with the pigment and the driving force is provided by the solvent evaporation. The long term stability of the pigment requires a non-polar solvent system like the aromatic hydrocarbons; however, the leafing action performs better in polar solvents like ketones and alcohols. Therefore, the coating formulation must consist of only non-polar solvents, while at the time of application, the material is thinned with polar solvents. Using this concept, the optimum PVC for the aluminum was determined to be 40%. These formulations and test results also appear in Tables VII, VIII, & IX.

The final experimental zinc and aluminum coatings were compared to samples of TT-P-28. This information is shown in Tables X & XI. During the thermal cycling test one of the TT-P-28 coatings failed and was dropped from further testing. The results for the rest of the physical tests indicated that the experimental coatings performed slightly better than the currently-used materials. The salt-spray corrosion test results also showed that the zinc coatings performed better than the TT-P-28 and the performance of the aluminum coatings was comparable to the standard coatings. When evaluating the test panels with the zinc dust, there was a white residue on the surface of the panels. This product is ZnO and is the result of the sacrificial chemical nature of the zinc pigment. The aluminum coatings had small areas where the coating failed, but provided good barrier protection over the rest of the panel surface.

The zinc-dust provided good chemical protection to the substrate and as stated previously, the aluminum pigment provided good barrier protection. Based on these two observations, it was decided to try both pigments in the same coating. The pigments were mixed in volume ratios of 3:1, 1:1 and 1:3; at PVC levels of 30% and 40%. The information for these coatings appears in Tables XII, XIII, & XIV. As stated before, a non-polar solvent system was used for the coating formulations; and, polar solvents were used to thin for application. General film properties for these formulations were similar, providing little distinction between these coatings and the previous materials. However, the corrosion resistance properties of the binary pigment system coatings were far better than those for the individually pigmented coatings. Further analysis of these results showed that the 1/1 pigment volume ratio with a total PVC of 40% was the optimum coating formulation.

The final coating was prepared by first milling the zinc-dust pigment in the resin system using only non-polar solvents. Then, the leafing aluminum pigment was mechanically stirred into the coating. Finally, when appling the coating using coventional air-spray, a polar solvent system was used to thin the material, while continually being mechanically stirred.

TABLE X COMPARISON OF SINGLE PIGMENT COATING PROPERTIES

Executive property of the prop

	DI-WATER (77 F)	단	P	ď	ď
STANCE	MIL-L-23699 (250 F)	P	d	d	<u>σ</u> .
FLUID RESISTANCE	JP-5 FUEL MIL-H-83282 (77 F) (150 F)	ď	đ	ď	G.
	JP-5 FUEL (77 F)	Ь	d	P	a.
	GE IMPACT FLEXIBILITY %elongation	-	1	40	20
THERMAL	CYCLING (5 Days @ 700F)	Cz.,	d.	G.	ď
	rests sckape (Kgms)	1.0	<.5	1.0	1.0
	ADHESION FESTS DRY/WET SCRAPE TAPE (Kgms)	સં / ત	d / d	d / d	а/а
;	DRY-HARD TIME (Hrs)	2.5	1.25	1.0	1.0
	NADC DRY-HAI IDENTIFICATION TIME NUMBER (Hrs)	TT-P-28-#1	TT-P-28-#2	FORMULATION NO. 8372- 50-Z1-25-A4	FORMULATION NO. 8372- 50-A5-25-A4/P

TABLE XI SINGLE PIGMENT COATINGS CORROSION RESISTANCE PROPERTIES ASTM METHOD #B 117 - 5% NaCl SALT SPRAY TEST UNPRETREATED STEEL SUBSTRATE - 500 HOURS

COATING ID	SCRIBE AREA	GENERAL COATING SURFACE
TT-P-28-#1	5 - WHR	Many spots of corrosion on surface with heavy rundown, in addition to heavily corroded areas where the coating lifted
TT-P-28-#2	5 – WHR	Many spots of corrosion with heavy rundown over the surfaces of both test panels
FORMULATION NO. 8372- 50-21-25-A4	2,3	White residue over the surfaces of both panels with approximately 20 small spots of corrosion on panel
FORMULATION NO. 8372- 46-A5-25-A5(P)	5 - WR	Approximately 100 very small spots of corrosion on the surfaces of both panels with some slight rundown

SCRIBE RATINGS:

- 1 No corrosion in scribe 2 Slight corrosion in scribe 3 Some corrosion in scribe 4 Moderate corrosion in scribe
 - 5 Heavy corrosion in scribe
- WR With rundown from scribe WHR With heavy rundown from scribe

TABLE XII ZINC DUST/ALUMINUM COATING SERIES FORMULATIONS

NA DC		RESINS		P16	P [GMENTS		SOLVENTS	VTS	PIGMENT
NO. 8372-	SR141	SR125	385~50E	101NZ	ALCAN 515	TOLUENE	MEK	ACETATE	CONC.
64-A/2-25-3/1	4.2	31.8	6.4	20.6	37.0	10	3	9	40
64-A/Z-25-2/2	3.9	29.4	5.9	38.0	22.8	10	3	9	40
64-A/Z-25-1/3	3.6	27.3	5.5	53.0	10.6	10	3	9	07
71-2/A-25-3/1	6.4	36.9	7.4	76.0	4.8	01	1	8	30
71-2/A-25-2/2	5.5	41.2	8.2	34.3	10.8	10		8	30
71-2/A-25-1/3	6.2	7.97	9.6	19.4	18.3	01	1	8	30
					¥				

NADC 87171-60

TABLE XIII ZING DUST/ALUMINUM COAFING SERIES PROPERTIES

			NADC	87171-60	·	
DI-WATER (77 F)	a.	œ,	ď	ā.	م.	۵ų
STANCE MIL-L-23699 (250 F)	e.	d.	G.	ď	વ	Q.
FLUID RESISTANCE MIL-H-83282 MIL-L (150 F) (25	a.	ď	ď	Ь	P	d.
JP-5 FUEL (77 F)	e.	Р	Ь	d	Р	ď
GE IMPACT FLEXIBILITY elongation (%)	60	09	70	60	09	09
THERMAL CYCLING (5 Days @ 700F)	ď	d	ď	d	ð.	a.
TESTS SCRAPE (Kgms)	1.0	1.0	1.0	1.0	1.0	1.0
ADHESTON TESTS DRY/WET SCRAPE TAPE (Kgms)	d / d	d / d	d / d	а / а	d / d	d / d
DRY-HARD TIME (Hrs)	1.0	1.0	1.0	1.0	1.0	1.0
NADC FORMULATION NO. 8372-	64-A/2-25-3/1	64-A/2-25-2/2	64-4/2-25-1/3	71-2/A-25-3/1	71-2/A-25-2/2	71-2/A-25-1/3

TABLE XIV ZINC DUST/ALUMINUM COATINGS CORROSION RESISTANCE PROPERTIES ASTM METHOD #B 117 - 5% NaCl SALT SPRAY TEST UNPRETREATED STEEL SUBSTRATE - 500 HOURS

FORMULATION NO. 8372-	SCRIBE AREA	GENERAL COATING SURFACE
54-A/Z-25-3/1	3 - WR	A number of small spots of corrosion on the surfaces of both panels with some slight rundown
64-A/Z-25-2/2	1	No evidence of any corrosion on the coating surface of either test panel
64-A/Z-25-1/3	2	Some small spots of corrosion on the surfaces of both panels with a slight trace of some rundown
71-Z/A-25-3/1	2	Some small spots of corrosion on the surfaces of both panels with a slight trace of some rundown
71-Z/A-25-2/2	3 - WR	Only a few spots of corrosion on the coating surface of both test panels
71-Z/A-25-1/3	4 – WR	Many small spots of corrosion on the surfaces of both panels with some slight rundown

SCRIBE RATINGS:

- 1 No corrosion in scribe
 2 Slight corrosion in scribe
 3 Some corrosion in scribe
 4 Moderate corrosion in scribe 5 - Heavy corrosion in scribe
- WR With rundown from scribe WHR With heavy rundown from scribe

DISCUSSION OF COMPARISON OF HTC'S PERFORMANCE

The final coating formulations were evaluated against several high temperature coatings, consisting of two samples of TT-P-28 and two high temperature coatings (HTC) submitted from industry. The properties of these materials were compared after exposure to four different thermal conditions. These thermal conditions were: the five day 70 to 700° F cycle; the five day 70 to 400° F cycle; one hour at 700° F; and seven days at room temperature (77° F). Standard coating tests were performed on coated steel test panels and this information appears in Tables XV to XXII.

Physical test results for the coatings exposed to the 70 to 700°F cycle are summarized in Table XV. Some of the specimens for the TT-P-28-#1 sample failed the thermal cycling test. This coating also failed the water resistance and wet tape adhesion tests. The other sample of TT-P-28, however, passed all of these tests. This indicated a possible quality control problem with this specification material. Further analysis of the test data showed that while all the coatings passed the thermal cycling, tape adhesion and fluid resistance tests, the developed coating dried faster, had a higher impact flexibility rating and better scrape adhesion than the TT-P-28 coatings and the industry HTC's. Salt spray tests were conducted on painted steel panels for 500 hours. See Table XVI for these results. The scribe areas of the experimental coatings showed little to no evidence of corrosion, while the rest of the specimens had heavy corrosion throughout the scribe area with heavy rundown of corrosion products from the scribe. The results for the general surface area also showed significant differences in performance between the coatings. The industry HTC's were as badly corroded as the uncoated blank panels. TT-P-28 panels had many spots of corrosion over the surface with excessive rundown from the spots, covering the majority of the panel. The developed coatings, however, had only a few spots of corrosion on some panels and none on the panels with the #25 resin system. Figure 4 shows the test specimens after salt spray exposure illustrating these differences.

Tables XVII and XVIII contain the data for the one hour at 700°F exposure condition. Again, the TT-P-28-#1 sample failed the thermal conditioning, and therefore, no further testing was performed on these specimens. The other TT-P-28 material failed both dry and wet tape adhesion tests and performed poorly in the scrape adhesion and impact flexibility tests. The HTC-1 passed the tape adhesion tests, but performed similar to the TT-P-28-#2 in the other tests. Under this condition, the experimental coatings were slightly less flexible than those obtained under the five day 700°F cycle. In addition, there was removal of very small areas at the films surface in some of the tape tests. Since this removal occurred only at the surface of the film, it was not significant enough to be considered a failure. The remaining properties of the coatings under this thermal exposure were the same as those conditioned under the five day 700°F cycle. Finally, the HTC-2 performed slightly better than the in-house coatings in the flexibility and tape tests and similarly in the rest of the physical tests. All of the coatings passed the fluid resistance tests. The corrosion resistance test results showed that the TT-P-28 and the HTC's performed as poorly as they did under the more severe thermal conditioning above. The NADC coatings, in these tests, displayed better performance than the other materials with only a slight decrease in the quality of protection provided as compared to the specimens exposed to the 70 to 700°F condition.

(77 F)WATER -IQ بعا д а а Q, FLUID RESISTANCE (250 F) 23699 MIL-L-Ч Ы Ы Δ, Ь MIL-H-83282 (150 F) Ы Ы Ы ٦ (77 F) (5 DAY - 700F Cycle) JP-5 ď Ы Ы а ۵ ۵ а FLEXIBILITY IMPACT (% Elong.) 1/2 9 40 9 20 SE ADHESION TESTS
DRY/WET SCRAPE
TAPE (Kgms) COMPARISON OF HIGH TEMPERATURE COATINGS 1.0 2.0 1.0 <.5 0.5 <.5 1.0 DRY/WET TAPE Ţ, 4 ď 3 Ч ď 3 Ы а THERMAL CYCLING (5 Days @ 700F) بعر Q, ۵ Д م ď ۵ DRY-HARD TIME (Hrs) 1.25 2.5 1.0 1.0 1.0 2.5 1.5 COATING I DENTIF ICATION TT-P-28-#1 TT-P-28-#2 A/Z-22-2/2 A/Z-25-2/2 A/Z-8-2/2 HTC-2 HTC-1 ⋧ TABLE

TABLE XVI CORROSION RESISTANCE TEST RESULTS (5 DAY - 700F Cycle)

TEST CONDITIONS:

ASTM #B 117, 5% NaC1 SALT SPRAY SUBSTRATE: UNPRETREATED 1020 STEEL

500 HOURS EXPOSURE

NADC COATING IDENTIFICATION	SCRIBE AREA	GENERAL COATING SURFACE
TT-P-28-#1	5 - WHR	Many spots of corrosion over the surfaces of both panels with excessive rundown
TT-P-28-#2	5 - WHR	Many spots of corrosion over the surfaces of both panels with excessive rundown
A/Z-8-2/2	2 - WR	A few spots of corrosion on both panel surfaces with slight rundown
A/Z-22-2/2	2	A few small spots of corrosion on both panel surfaces with no rundown
A/Z-25-2/2	l , 2	Vertually no evidence of corrosion on the surface of either panel
HTC-#1	5 – WHR	Surfaces of both panels were completely corroded as the blank
HTC -#2	5 – WHR	Surfaces of both panels were completely corroded as bad as the blank

SCRIBE RATINGS:

1 - No corrosion in scribe

2 - Slight corrosion in scribe

3 - Some corrosion in scribe

4 - Moderate corrosion in scribe


5 - Heavy corrosion in scribe

WR - With rundown from scribe

WHR - With heavy rundown from scribe

120 HRS THERMAL CYCLING BETWEEN ROOM TEMPERATURE AND 700°F 500 HRS IN 5% NaCI SALT SPRAY PRE-CONDITIONING: **EXPOSURE:**

BARE 1020 STEEL **SUBSTRATE:**



COATING

FIGURE 4.

TEST PANELS FOR CORROSION RESISTANCE TEST.

TABLE XVII COMPARISON OF HIGH TEMPERATURE COATINGS (1 HOUR @ 700 F)

COATING IDENTIFICATION	DRY-HARD TIME (Hrs)	THERMAL EXPOSURE 1 Hour @ 700F	ADHESION TESTS DRY/WET SCRAP TAPE (Kgms	TESTS SCRAPE (Kgms)	FLEXIBILITY GE IMPACT (% Elong.)	JP-5 FUEL (77 F)	FLUID R MIL-H- 83282 (150 F)	RESISTANCE MIL-L- 23699 (250 F)	DI- WATER (77 F)
TT-P-28-#1	2.5	Ĉt.	ત / વ	-					
TT-P-28-#2	1.25	Ь	F / F	<.5	5	Ь	d	ď	д
A/Z-8-2/2	1.0	Ь	* / P	1.0	40	Ь	ď	Δ.	Δ,
A/Z-22-2/2	1.0	ď	* / *	1.0	10	d	Ч	d	ď
A/Z-25-2/2	1.0	ď	4 / P	1.0	20	d	C.,	Δ,	ē.
HTC-1	2.5	Ь	д / д	0.5	<0.5	ď	d	d	ē.
HTC-2	1.5	a،	d / d	1.0	09	d	C.	C-I	£.
		4			T				

* SLIGHT REMOVAL OF SOME OF THE COATING'S SURPACE

TABLE XVIII CORROSION RESISTANCE TEST RESULTS (1 HOUR @ 700 F)

TEST CONDITIONS:

ASTM #B 117, 5% NaCl SALT SPRAY SUBSTRATE: UNPRETREATED 1020 STEEL

500 HOURS EXPOSURE

NADC COATING IDENTIFICATION	SCRIBE AREA	GENERAL COATING SURFACE
TT-P-28-#1	FAILED THERMAL CYC	CLING - NOT TESTED
TT-P-28-#2	5 – WHR	Many spots of corrosion over the surfaces of both panels with very fine rundown
A/Z-8-2/2	4 – WR	Many small spots of corrosion on both panel surfaces with some light rundown
A/Z-22-2/2	4 – WR	Some small spots of corrosion on the surfaces of both panels with some light rundown
A/Z-25-2/2	3 - WR (Slight)	Some small spots of corrosion on the surfaces of both panels with some light rundown
HTC-#1	5 – WHR	Surfaces of both panels were completely corroded as bad as the blank
HTC-#2	5 - WHR	Surfaces of both panels were completely corroded as bad as the blank

SCRIBE RATINGS:

1 - No corrosion in scribe 2 - Slight corrosion in scribe 3 - Some corrosion in scribe 4 - Moderate corrosion in scribe

5 - Heavy corrosion in scribe

WR - With rundown from scribe WIR - With heavy rundown from scribe

In the five day $400/500^\circ F$ thermal series, the physical test results were approximately the same as those obtained for the five day $700^\circ F$ thermal series, with the exception that both TT-P-28 samples passed the thermal cycling test. Again, the developed coatings performed the best in these tests, as can be seen in Table XIX. Also, the results obtained for the corrosion resistance test, shown in Table XX, were comparable to the ones for the one hour at $700^\circ F$ series.

Finally, the coatings were evaluated after one week of room temperature exposure and no thermal conditioning. This data shown in Table XXI, indicated that although the test results varied slightly, there were no real significant differences between the physical properties of the materials. However, one difference between the results for this condition and the other thermal conditions was that all of the coatings softened to some degree in the fluid resistance test. Information for the corrosion test appears in Table XXII. The industry coatings, again, were as bad as the uncoated blank panels in these tests. The scribe areas for the TT-P-28 were similar to the HTC's, while the general surface areas were slightly better than the HTC's in appearence. The scribe areas for the in-house coatings were better than the other films, although, the general surface areas were only comparable to the TT-P-28 materials.

In general, throughout all of the tests under all of the conditions in this investigation, the NADC coating outperformed both the TT-P-28 coatings and the industry high temperature coatings. In this investigation, some interesting trends were apparent from analyzing all of the test data. The most significant trend is that the more severe the thermal conditioning became, the better the developed coating performed. Before thermal exposure, its performance is comparable with the TT-P-28 coatings, but with time and exposure, the experimental coatings performance far exceeded that of the other coatings. For the TT-P-28, however, only some of the properties improved with thermal conditioning, while the corrosion resistance decreased with severity of exposure. Finally, the industry high temperature materials steadily decreased in performance with exposure.

STREET STREET, STREET,

CONCLUSIONS

essential appropriate contract appropriate appropriate appropriate and appropriate appropr

The developed coating has demonstrated improved performance in laboratory tests over the currently-used materials. It can be spray-applied to matallic substrates and provides excellent corrosion protection. In addition, the ease of application and ability to be used without a high temperature cure makes this coating a practical alternative to the standard TT-2-18 and Sermatel Whigh-temperature materials.

FUTURE EFFORTS

Service testing of this material is planned to begin in the last quarter of 1987 and continue through to 1989. Upon the successful completion of the field evaluation, the developed coating will be transitioned into fleet use through the preparation of a military specification.

TABLE XIX COMPARISON OF HIGH TEMPERATURE COATINGS (5 DAY - 400/500F CYCLE)

DI- WATER (77 F)	Ь	ď	Ь	Ь	ď	Ь	Ь
FLUID RESISTANCE IL-H- MIL-L- 83282 23699 150 F) (250 F)	Ь	Ь	Ь	Ь	ď	d	ď
FLUID R MIL-H- 83282 (150 F)	ď	d	Ь	ď	d	d	ď
JP -5 FUEL (77 F)	d	d	d	Ь	ď	ક્ષ	ď
FLEXIBILITY GE IMPACT (% Elong.)	1	1	09	09	69	<0.5	20
N TESTS SCRAPE (Kgms)	<5	?* >	1.0	1.0	1.0	0.5	0.5
ADHESTON TESTS DRY/WET SCRAPE TAPE (Kgms)	d / *	d / d	d / d	d / d	d / d	4 / 4	a / a
CYCLING S DAY 70- 400/500F	ď	đ.	d.	đ.	d	Q.	ð.
DRY HARD TIME (Hrs)	2.5	1.25	1.0	1.0	1.0	2.5	1.5
COATING IDENTIFICATION	TT-P-28-#1	TT-P-28-#2	A/2-8-2/2	A/Z-22-2/2	A/Z-25-2/2	IFTC-1	IITC~2

* SLIGHT REMOVAL OF SOME OF THE COATLING'S SHREACE

TABLE XX CORROSION RESISTANCE TEST RESULTS (5 DAY - 400/500 F)

TEST CONDITIONS:

ASTM #B 117, 5% NaCl SALT SPRAY SUBSTRATE: UNPRETREATED 1020 STEEL

500 HOURS EXPOSURE

NADC COATING IDENTIFICATION	SCRIBE AREA	GENERAL COATING SURFACE
TT-P-28-#1	5 ~ WHR	Many spots of corrosion over the surfaces of both panels with very fine rundown
TT-P-28-#2	5 ~ WHR	Many spots of corrosion over the surfaces of both panels with very fine rundown
A/Z-8-2/2	4 – WR	Many small spots of corrosion on both panel surfaces with some light rundown
A/Z-22-2/2	4 ~ WR	Small spots of corrosion on the surfaces of both panels with some light rundown
A/Z-25-2/2	3,4 - WR	Small spots of corrosion on the surfaces of both panels with some light rundown
HTC ~#1	5 ~ WHR	Surfaces of both panels were completely corroded as bad as the blank
HTC-#2	5 - WHR	Surfaces of both panels were completely corroded as bad as the blank

SCRIBE RATINGS:

1 - No corrosion in scribe
2 - Slight corrosion in scribe
3 - Some corrosion in scribe
4 - Moderate corrosion in scribe

5 - Heavy corrosion in scribe

TR - With heavy rundown from scribe WHR - With heavy rundown from scribe

TABLE XXI COMPARISON OF HIGH TEMPERATURE COATINGS (7 DAYS @ 70 F)

DI- WATER (77 F)	*	+ k	*	*	*	*	- *
RES ISTANCE MIL-L- 23699 (250 F)	*	*	*	*	*	*	*
FLUID R MIL-H- 83282 (150 F)	÷	*	*	*	*	*	*
JP-5 FUEL (77 F)	*	*	*	*	*	*	- ×
FLE XIB ILITY GE IMPACT (% Elong.)	20	20	09	09	09	10	20
v TESTS SCRAPE (Kgms)	2.0	2.0	1.0	0.5	0.5	<0.5	2.0
ADHESION TESTS DRY/WET SCRAPE TAPE (Kgms)	Р / Р	д / д	d / d	Р / Р	Р/Р	д / д	P / F
NO THERMAL CYCLING (77 F)				-			
DRY-HARD TIME (Hrs)	2.5	1.25	1.0	1.0	1.0	2.5	1.5
COATING IDENTIFICATION	TT-P-28-#1	TT-P-28-#2	A/2-8-2/2	A/2-22-2/2	A/2-25-2/2	HTC-1	HTC-2

* ALL COATINGS SOFTENED TO SOME DEGREE

TABLE XXII CORROSION RESISTANCE TEST RESULTS (7 DAYS @ 70 F)

TEST CONDITIONS:

ASTM #B 117, 5% NaCl SALT SPRAY SUBSTRATE: UNPRETREATED 1020 STEEL

500 HOURS EXPOSURE

NADC COATING IDENTIFICATION	SCRIBE AREA	GENERAL COATING SURFACE
TT-P-28-#1	5 - WHR	Many spots of corrosion covering the entire surfaces of both panels with very fine rundown
TT-P-28-#2	5 - WHR	Many spots of corrosion covering the entire surfaces of both panels with very fine rundown
A/Z-3-2/2	5 ~ WR	Many small spots of corrosion on both panel surfaces with some light rundown
A/Z-22-2/2	5 ~ WR	Many small spots of corrosion on the surfaces of both panels with some light rundown
A/Z-25-2/2	4 ~ WR	Many small spots of corrosion on the surfaces of both panels with some light rundown
HTC-#1	5 - WHR	Surfaces of both panels were completely corroded as bad as the blank
HTC -#2	5 - WHR	Surfaces of both panels were completely corroded as bad as the blank

SCRIBE RATINGS:

1 - No corrosion in scribe 2 - Slight corrosion in scribe 3 - Some corrosion in scribe 4 - Moderate corrosion in scribe

5 - Heavy corrosion in scribe

WR - With rundown from scribe WHR - With heavy rundown from scribe

REFERENCES

- (1) "Strategy of Formulation Development," a Short course offered by E.I. Dupont Inc.
- (2) C. R. HEGEDUS and A. T. Eng, "Optimization of Binary Pigment Coatings," NADC Report No. NADC-87008-60, 5 January 1987.
- (3) T. C. Patton, "Pigment Handbook," Wiley-Interscience, New York, 1973.

ACKNOWLEDGEMENT

The author would like to express his appriciation to Mr. Anthony Eng of the Protective Coatings Team for his assistance in the laboratory evaluation of this experimental coating.

Rockwell International Attn: L.Streett, Dept. 871 4300 E. 5TH Ave. Columbus, OH 43216	1
Sherwin Williams Attn: G. Bierwagon 10909 S. Cottage Grove Ave. Chicago, IL 60628	1
Sterling Laquer Attn: G. Halet 3150 Brannon Ave. St. Louis, MO 63139	1
Titanine Div Attn: C. Scaturo 320 Paterson Plank Rd. Carlstadt, NJ 07072	1
U.S. Paints Attn: J. Lott 331 S. 21ST St. St. Louis, MO 63103	1
Warner-Robbins Air Logistics Command (MMEMC, MMTRC) Robbins AFB, GA 31098	2
Wright Aeronautical Laboratories (MLSA) Wright-Patterson AFB, OH 45433-6533	1
NAVAIRDEVCEN (30 for 6062 3 for 8131, 1 for 60C2)	3 4

Naval Aviation Depot (342) Naval Air Station Alameda, CA 94501	1
Naval Aviation Depot (343) Naval Air Station Jacksonville, FL 32212-0016	1
Naval Aviation Depot (343) Naval Air Station Norfolk, VA 23511-5188	1
Naval Aviation Depot (342) Naval Air Station Pensacola, FL 32508	1
Naval Aviation Depot (34210) Naval Air Station, North Island San Diego. CA 92135-5100	1
Naval Civil Engineering Laboratory (L52) Port Hueneme, CA 93043	1
Naval Facilities Engineering Command (032) 200 Stovall Street Alexandria, VA 22332-2300	1
Naval Research Laboratory (6120, 6123. 6124) 4555 Overlook Avenue Washington, DC 20375	3
Naval Sea Systems Command (SEA-05M1) Washington, DC 20362	1
Office of Naval Research (431, 12) 300 North Quincy Street Arlington, 7A 22217-5000	2
Office of Naval Technology (ONT-225) 800 North Quincy Street Arlington, VA 22217-5000	1
Pfizer Inc. Attn: D. Towhi'l 640 N. 13TH St. Easton, PA 13042	1
Pratt and Lambert Attn: S. Mack 16116 E. 13TH St. Wickita, KS 67201	ì

Koppers Inc. Attn: F. Winkelman 480 Frelinghuysen Ave. Newark, NJ 07114	1
Lehigh University (H. Leidheiser) Bethlehem, PA 18015	1
Lenmar Inc. Attn: M. Sandler 150 S. Calverton Rd. Baltimore, MD 21223	l
Lockheed-GA Attn: B. Bradley 86 S. Cobb Drive, Dept. 72-27 Marietta, GA 30063	1
Marine Corps Air Station (342) Cherry Point, NC 28533-5030	1
Martin Marietta Labs Attn: J. Venables 1450 S. Rolling Rd. Baltimore, Md 21227	l
McCloskey Varnish Co. Attn: R. Frusco 7600 State Rd. Phila., PA 19136	l
McDonnel Douglas Attn: B. Williams St. Louis, MO	1
Mobay Themical Attn: B. Sylvester Penn-Lincoln Parkway West Pittsburg, Pa 15205	:
National Bureau of Standards (M. McKnight) Washington, DC 20234	1
Naval Air Engineering Center (9321) Lakehurst, NJ 08733-5100	•
Naval Air Station (AIRLANT-528) Norfolk, VA 23511-5138	,
Naval Air Station, North Island (AIRPAC-7412) San Diego, CA 92135-5100	1
Naval Air Systems Command (AIR-41121E. AIR-5304D) Washington, DC 20361	2

David Taylor Naval Ship Research & Development Center (2813, 2841) Annapolis. MD 21402-5067	2
Defense Technical Information Center Cameron Station Alexandria, VA 22314	1 2
Deft Inc. Attn: B. Levine 17451 Von Karman Ave. Irvine, CA 92714	1
Desoto Inc. Attn: B. Byrd 1700 S. Mount Prospect Rd. Des Plains, IL 60018	1
Dexter Corp. Attn: B. Harlman 31500 Hayman St. Haywood, CA 94544	1
Enterprise Chemical Attn: S. Kish 1191 S. Wheeling Rd. Wheeling, IL 60090	1
General Dynamics Attn: J. Peoples P.O. Box 743 Ft. Worth, TX 76101	1
General Electric Attn: P. Lavin Silicone Rd. Waterford, NY 12188	1
Gruman Aerospace Corp. Attn: G. Kelley Bethpage, NY 11714	1
Hercules Inc Coatings Attn: R. Wint 910 Market St. Wilmington, DE 19899	1
Hughson Chemicals Attn: A. Patterson 2000 W. Grandview Blvd. Erie, PA 16512	l

DISTRIBUTION LIST NADC-87171-60	
	Copies
Advanced Coatings Attn: T. Corboy	1
4343 Temple City Blvd. Temple City, CA 91780	
Alox Corp. Attn: D. knowlton 3943 Buffalo Ave. Niagra Falls, NY 14302	1
American Cyanamide Attn: J. Bennett Bound Brook NJ 08805	1
Ameron-Prot. Coat. Attn: F. Farrell 201 N. Berry St. Brea, CA 92621	1
Army Aviation Systems Command (DRDAV-DS) 4300 Goodfellow Boulevard St. Louis, MO 63120-1798	1
Army Belvoir Research & Development Center (STE Fort Belvoir, VA 22060-5606	RBE-VO) 1
Army Materials Technology Laboratory (DRXMR-MM) Watertown, MA 02172	1
BASF-Wyndot Corp. Attn: M. Nienhuis 491 Columbia Ave. Holland, MI	i
Boing Aerospace Attn: W. Hamilton P.O. Box 3999 Seattle, WA 98124	1
Bostik Div. Attn: K. Silberger 20846 S. Normandie Ava. Torrance, CA 90502	1
Ciba-Geigy Corp. Attn: R. Varron Ardsley, NY 10502	1

F/V/))AIL - ILMED 5-88 071C